Work Orde	er ID 83620 7:38 PM		*83620*								=
Item ID: Revision ID:	D412-742-043		Accept	*N900	040	100	)* s	Setup Sta	rt <b>*N</b>	S1*	=
Item Name:	Replacement Float Skidtube							Sto	P *N	S2*	
Start Date: Required Date:	20/04/2012 Start Qty: 1.0 04/05/2012 Req'd Qty: 1.0	•		Cust Item I Customer:	<b>D:</b> .					***	
Reference:		5. ** **									
Approvals:	Process Plan: MUJ	Date: \\ \Z \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	ZO Tooling:	Da	ate:	_	R	Run Sta	. "IZI	R1*	
	QC:	Date:/	<b>SPC (Y/N):</b>	Da	ate:		*	Sto	<sup>p</sup> *N	R2*	
Sequence ID/ Work Center ID	Operation Description		Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp	_
Draw Nbr	Revision Nbr										-
D3391	l								.1		
100			0.00				•			<u>.</u>	-
*100* DC	DOCUMENT CON	TROL	0.00					<del></del>			
Document Control		-742-043 is a W/O on it's ow py bluefile and create labels		SHG005							

Dart Ae	rospace Lt	d						•	•.
W/O:			WC	RK ORDER CHANGE	S		<del></del>		-
DATE	STEP	PR	OCEDURE CHAI	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approva QC Inspecto
Part No	:	PAR #:	Fault Cate	gory:	NCR: Yes	No DQ	A:	Date: _	
	Reso	lution:	Disposition	1:	QA: N/C CI	osed:		Date: _	
NCR:			WORK ORD	ER NON-CONFORMAN	ICE (NCF	R)	1		
DATE	STEP	Description of NC		Corrective Action Section		Verific	ation	Approval	Approva
DATE	SIEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign 8 Date	Section	on C	Chief Eng	QC Inspecto
							. :		
		<b>3</b>							
	71.					3			

Work Order ID 83620  April-20-12 2:27:38 PM				*83	320*				-			Page 2		
Item ID: Revision ID:	D412-742-0	43				Accept	*N900	040	100	)*	Setup	Start	*N	S1*
Item Name:	Replacement	Float Skidtu	ıbe									Stop	*N	S2*
Start Date: Required Date: Reference:	20/04/2012 04/05/2012	_	ty: 1.00 Oty: 1.00		*1* *1*		Cust Item I Customer:	D:						
Approvals:	Process Pla	an:		Date:		Tooling:	Da	ate:	_	]	Run	Start	*N	R1*
	QC:			_ Date:		_ SPC (Y/N):		ate:				Stop	*N	R2*
Sequence ID/ Work Center ID 110	)	Operation Descript				Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Rej Qty		Reject Number	Insp. Stamp
*110* HandFinish		HandFinish	ning Memo			0.00					\$		JU A	105/29
Hand Finishing		/	241/291. Er 7/16" "T" Pi A/RSikaflex Expiry date: 2-Install wea	nsure tube end ns. -241/-291 // -13/03 urplates as per	s line-up wi 121469 — Dwg D3391	all the way around using th saddle holes for prope	r alignment, using							•
		/	ones with ins	-241/-291 /	of tube ,har	nd tighten only bolts wit	h no sikaflex.							
·				Γ" pins once s  posed hardwa		y.  Procyon. Remove any o	excess off with							
		/	MEK degrea	ser. cyon/\/ /\										

Dart Ae	rospace l	Ltd					B		
W/O:			WO	<b>RK ORDER CHANG</b>	ES		1		
DATE	STEP	PRO	CEDURE CHAN	IGE	Ву		Date Q	ty Approval Chief Eng / Prod Mgr	Approva QC Inspecto
			.,,, 48				i'		
Part No	);	PAR #:	Fault Categ	ory:	_ NCR: Yes	s N	o <b>DQA:</b> _	Date: _	· · · · · · · · · · · · · · · · · · ·
•	Res	solution:	Disposition	:	_ QA: N/C	Clos	ed:	Date: _	
NCR:		· .	WORK ORDE	R NON-CONFORM	ANCE (NC	R)			
	T	Description of NC		Corrective Action Sect	on B		Verification	on Approval	Approva
DATE	STEP	Section A	<b>Initial</b> Chief Eng	Action Description Chief Eng	Sign Dat		Section C		QC Inspect
				•					
							. , "		
							:		
					· · · · · · · · · · · · · · · · · · ·		<u> </u>		1

<b>Work Ord</b> April-20-12 2:2		620		*836	320*		a				Page 3
Item ID: Revision ID: Item Name: Start Date:	D412-742-04 Replacement F 20/04/2012		*1*	Accept	*N900		100	)* s	etup Star Stop	IVI	S1* S2*
Required Date: Reference:	04/05/2012	Req'd Qty: 1.00	*1*		Customer:						
Approvals:		n:	Date:	Tooling: SPC (Y/N):	·	te:	- 	R	tun Star Stop	" <b>[V]</b> [	R1* R2*
Sequence ID/ Work Center II 120	D	Operation Description QC5- Inspect part compl	eteness to step on W/O	Set Up/ Run Hours	Tool ID	Tool#	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
*120* QC Quality Control		Memo		0.00							alf 120529
130		Poolsooine		0.00					ام	4.1	
*130* Packaging Packaging		Packaging  Memo  Identify and Location: PPP Rev:	pack for shipping as per F	0.00 PPP D412-742-043	(A) 83	fo18				ilsleof	<u></u>
<sup>140</sup> <b>*1⊿∩*</b>		QC21- Final Inspection -	Work Order Release	0.00					AAI S	1010	~ 1 30
QC Quality Control		Мето		0.00						MK	20

## 

NCR:		WORK ORDER NON-CONFORMANCE (NCR)									
·		Description of NC		Corrective Action Section B			Verification	Approval	Approval		
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sigr Da		Section C	Chief Eng	QC Inspector		
			·								
	,	•									
		,									
				•					}		
		•					η				
		. )									

Work Order ID: 83620

\*83620\*

Parent Item:

D412-742-043

\*D412-742-043\*

Parent Item Name: Replacement Float Skidtube

**Start Date: 20/04/2012** 

**Required Date:** 04/05/2012

Start Qty: 1.00

Required Qty: 1.00

**Comments:** 

IPP Rev A 05.10.13 New Issue

KJ/JLM

IPP Rev 06.02.13 ECN 773 dwg @ rev.D

EC

IPP Rev:C 07-05-28 As per Rev F

JLM

IPP Rev:D 07-12-04 ECN 1072

DD verified by:JLM

IPP Rev:E 08-09-08 ecn 08-510 DD verified by:EC

IPP Rev:F

11.11.01 as per DSI9517 REV.B DD verified by:EC

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
D3391-021		Manufactured	No			110	Each	0.0000	1	1			
*D3391-02 Fwd Tube Assembly	21*								** <u>P</u>	810c	17 (x1	) Yl	105/2
D3391-023		Manufactured	No			110	Each	1.0000	1	1			
*D3391-02	23*								**	3 837	276 (	<u> </u>	u nosl
				<b>Location</b>		Loc	Qty.	Loc Code					
				FP			2					•	
					31105		1		_		_		
D2201 025				GA			-1		_		-		
D3391-025		Manufactured	No			110	Each	1.0000	1	1	•	٠. ,	1
*D3391-03 Aft Tube Assembly	25*								**	<u>,836</u>	30 (x	() Je	l nlos
				Location		Loc	<u>Otv</u>	Loc Code					•
				FP001			1						
											-		

81111

Dart Ae	TOSPACE L								
W/O:			WO	RK ORDER CHANGES	3			,	
DATE	STEP	PR	OCEDURE CHAI	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approva QC Inspecto
Part No	:	PAR #:	Fault Cate	gory:	NCR: Ye	s No DO	QA:	Date: _	
				1:		ľ			
NCR:			WORK ORDE	R NON-CONFORMAN	CE (NO	CR)			
DATE	STEP	Description of NC		Corrective Action Section		Verif	ication	Approval	Approval
DAIE	SIEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sig Da	n& Ser	tion C	Chief Eng	QC Inspecto
_									
		·					· .		
	1 1								1
				•					
		·					<del></del>		

Picklist Print April-20-12 2:27:41 PM									Page 2
Work Order ID: 83620		*81	3620*						
<b>Parent Item:</b> D412-742-043			412-742-04	<b>1</b> 2*					
Parent Item Name: Replacemen	nt Float Skidtube	.,		<b></b> .,			t Date: 2 rt Qty: 1	0/04/2012 .00	Required Date: 04/05/2012 Required Qty: 1.00
AN3C4A	Purchased	No		110	Each	2,292.000	24	24	
*AN3C4A*						3	<b>*</b> *	Kl	12/05/23
			Location ST350 120187 120521 120769 121205	<u>f</u>	2292 1226 28 38 1000	<u>Loc Code</u> // 1 2 1 5 5 ( <sub>e</sub>			
AN3C6A	Purchased	No		110	Each	425.0000	10	10	
*AN3C6A*						7	<b>**</b>		12/05/27
			Location	. <u>L</u>	oc Oty	Loc Code			
			FP001		1				
			111982		1				
			ST351		424				
			.111982 116419		2	-			
			116549		23 2				
			116704		12				
			117619		10				
			117688		1				
			117872		5				
			118422		13				
			119449		21				

Dart Ae	rospace	e Ltd					•	•
W/O:			WC	RK ORDER CHANGES	3			
DATE	STEP	PR	OCEDURE CHA	NGE	Ву	Date Qty	Approval Chief Eng / Prod Mgr	Approva QC Inspecto
						, and the second		
Part No	):	PAR #:	Fault Cate	gory:	NCR: Yes	No DQA:	Date: _	
	R	esolution:	Disposition	n:	QA: N/C	losed:	Date: _	
NCR:			WORK ORDI	ER NON-CONFORMAN	CE (NCF	₹)		
DATE	STEP	Description of NC		Corrective Action Section		Verification		Approva
DATE	SIEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign a	Section C	Chief Eng	QC Inspecto
				~				

April-20-12 2:27:41 PM

Work Order ID: 83620 \*83620\* Parent Item: D412-742-043 \*D412-742-043\* Parent Item Name: Replacement Float Skidtube Start Date: 20/04/2012 **Required Date:** 04/05/2012 Start Qty: 1.00 Required Qty: 1.00 AN3C7A Purchased No 110 140.0000 Each \*AN3C7A\* \*\* 12/05/22 BOLT Location Loc Qty Loc Code ST351 140 11121541 113149 14 116169 1 117313 10 117619 12 117688 119749 1. 120731 46 121185 50 AN960C10L NAS1149C0332 Purchased No 110 Each 0.0000 11/12/509 (x38). HI \*AN960C10I \* ✓ washer D4095-041 Manufactured 110 Each 3.0000 \*D4095-041\* \*\* Wearplate Assembly Location Loc Oty Loc Code FP001 3 B81623 3 78996 D4095-043 Manufactured No 110 Each 4.0000 \*D4095-043\* \*\* HI 12/05/22 Wearplate Assembly Location Loc Qty Loc Code FP001 1381624 78995

Dart Ae	rospace	Ltd								•
W/O:			WC	RK ORDER CHA	NGES					
DATE	STEP	PRO	OCEDURE CHAI	NGE	В	y	Date	Qty	Approval Chief Eng / Prod Mgr	Approva QC Inspector
								**		
Part No		PAR #:								
	Re	esolution:	Disposition	n:	QA: N/	C Clo	sed:		Date: _	
NCR:			WORK ORDE	R NON-CONFOR	RMANCE (N	ICR)	)			
5.4		Description of NC		Section B		Verific	cation	Approval	Approval	
DATE	STEP	Section A	Initial Chief Eng	Action Descripti Chief Eng		gn & Date		on C	Chief Eng	QC Inspecto
_								•	·	
·								•		
			i i					* <sub>0</sub>		
								<del>-                                    </del>	:.	
	1						į			
,						į.				
				•						

Ρi	ck	lic	t	P	ri	nı	f
							Ł

April-20-12 2:27:41 PM

Page 4

Work Order ID: 83620

Parent Item:

D412-742-043

\*83620\*

\*D412-742-043\*

Parent Item Name: Replacement Float Skidtube

**Start Date: 20/04/2012** 

**Required Date:** 04/05/2012

Start Qty: 1.00

Required Qty: 1.00

D4095-045

Manufactured

110

16.0000

Each


\*\*

\*D4095-045\*


Wearplate Assembly

Location	<u>1</u>	Loc Qty	Loc Code
FP		15	
	<u>81625</u>	15	
FP001		1	
	77737	1	


## **Dart Aerospace Ltd** W/O: **WORK ORDER CHANGES Approval Approval PROCEDURE CHANGE** DATE STEP By **Date** Qty Chief Eng / QC Inspector Prod Mgr Part No: \_\_\_\_\_ PAR #: \_\_\_\_ Fault Category: \_\_\_\_ NCR: Yes No DQA: \_\_\_ Date: \_\_\_\_ Resolution: \_\_\_\_\_ Disposition: \_\_\_\_\_ QA: N/C Closed: \_\_\_\_ Date: \_\_\_\_ WORK ORDER NON-CONFORMANCE (NCR) NCR: **Corrective Action** Section B **Description of NC** Verification **Approval** Approval **STEP** DATE Sign & Initial **Action Description** Section A QC inspector Section C Chief Eng Date Chief Eng Chief Eng




## **Dart Aerospace Ltd WORK ORDER CHANGES** W/O: **Approval Approval** DATE **STEP** By Qty PROCEDURE CHANGE Date Chief Eng / QC Inspector Prod Mar Part No: \_\_\_\_\_\_ PAR #: \_\_\_\_ Fault Category: \_\_\_\_\_ NCR: Yes No DQA: \_\_\_\_ Date: \_\_\_\_ Resolution: \_\_\_\_\_ Disposition: \_\_\_\_ QA: N/C Closed: \_\_\_\_ Date: \_\_\_\_ **WORK ORDER NON-CONFORMANCE (NCR)** NCR: **Corrective Action** Section B **Description of NC** Verification **Approval Approval** DATE **STEP** Sign & **Action Description** Initial Section A Section C Chief Ena QC Inspector Date Chief Eng Chief Eng




Dart Ae	rospace L	td					•		•
W/O:			WC	RK ORDER CHANG	GES				<del>.</del>
DATE	STEP	PRO	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approva QC Inspecto		
			<u>·</u>						
Part No		PAR #:	Fault Cate	Jory:	NCR: Ye	s No D	QA:	Date: _	
	Resolution:		Dispositio	QA: N/C	Closed: Date:				
NCR:		,	WORK ORDI	ER NON-CONFORM	ANCE (NO	CR)	<del>-</del>		
	T	Description of NC	Corrective Action Section B				Verification		Approva
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sigr Da	1&   c	Section C	Approval Chief Eng	QC Inspect
					-				
							·		
,								'	
		······································					······································		
								•	




## **Dart Aerospace Ltd** W/O: **WORK ORDER CHANGES Approval Approval** DATE **STEP PROCEDURE CHANGE** By Qtv Chief Eng / Date QC Inspector Prod Mgr Part No: \_\_\_\_\_\_ PAR #: \_\_\_\_ Fault Category: \_\_\_\_\_ NCR: Yes No DQA: \_\_\_\_ Date: \_\_\_\_ Resolution: \_\_\_\_\_ Disposition: \_\_\_\_ QA: N/C Closed: \_\_\_\_ Date: \_\_\_\_ WORK ORDER NON-CONFORMANCE (NCR) NCR: **Corrective Action** Section B **Description of NC** Verification **Approval Approval** DATE **STEP** Sign & **Action Description** Initial Section A Section C Chief Ena QC Inspector Date Chief Eng Chief Eng




rospace L	.td							<b>c</b>	
		WO	<b>RK ORDER CHANG</b>	ES					
STEP	PR	OCEDURE CHAI	IGE	Ву	Dat	e Qty	Approvai Chief Eng / Prod Mgr	Approva QC Inspecto	
:	PAR #:	Fault Cate	jory:	_ NCR: Yes	s No	DQA:	Date: _		
Resolution:			Disposition:			Closed: Date:			
		WORK ORDE	R NON-CONFORMA	NCE (NC	R)				
	Description of NC	Corrective Action Section B			Varification		Anneyel	Approva	
STEP	Section A	Initial Chief Eng	Action Description Chief Eng		ې ا&کا		Chief Eng	Approva QC Inspecto	
					-				
7									
1					-	,			
	STEP	PAR #: Resolution: STED Description of NC	STEP PROCEDURE CHAN  PROCEDURE CHAN  PAR #: Fault Categon  Resolution: Disposition  WORK ORDE  STEP Description of NC Section A Initial	STEP PROCEDURE CHANGE  PROCEDURE CHANGE  PROCEDURE CHANGE  Fault Category:  Disposition:  WORK ORDER NON-CONFORMA  STEP Description of NC Section A  Initial Action Description	WORK ORDER CHANGES  STEP PROCEDURE CHANGE By  PAR #: Fault Category: NCR: Yes  Resolution: Disposition: QA: N/C O  WORK ORDER NON-CONFORMANCE (NC  STEP Description of NC Section A Section B Initial Action Description Sign	STEP PROCEDURE CHANGE By Date  Description of NC Section A Section A Section B Sign & Volume of Not Section A Section B Sign & Volume of Not Section B Sign	WORK ORDER CHANGES  STEP PROCEDURE CHANGE By Date Qty  Description of NC Corrective Action Section B Section C Secti	WORK ORDER CHANGES  STEP PROCEDURE CHANGE By Date Qty Chief Eng/Prod Mgr  DESCRIPTION OF CORRECTION Section B Section C Sectio	




Dart Ae	rospace L	td							
W/O:			WC	RK ORDER CHANG	ES				
DATE	STEP	PROCEDURE CHANGE			Ву	Da	te Qty	Approval Chief Eng / Prod Mgr	Approva QC Inspect
<u>.</u>									
Part No	·:	PAR #:	Fault Cate	gory:	NCR: Ye	s No	DQA:	Date: _	
			Disposition: QA			Closed: Date:			
NCR:			WORK ORDE	R NON-CONFORMA	NCE (NC	R)			
		Description of NC	Corrective Action Section B			V	Approva		
DATE	STEP	TEP Description of NC Section A	Initial Chief Eng	Action Description Chief Eng	Sigr Da	ነ&	<b>Verification</b> Section C	Approval Chief Eng	QC Inspect
							•		
	<u> </u>								
							·		



Dart Ae	rospace l	_td							• •
W/O:			WC	RK ORDER CHANGES	S				
DATE	STEP	PR	OCEDURE CHAI	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approva QC Inspecto
									-
Part No: PAR #:			Fault Cate	gory:	NCR: Yes	No D	QA:	Date: _	
	Res	solution:	Disposition	1:	QA: N/C	losed: _	<u> </u>	Date: _	
NCR:			WORK ORDE	ER NON-CONFORMAN	ICE (NC	R)			- III
D. 4.7.	0755	Description of NC Section A	Corrective Action Section B			Veri	fication	Approval	Approva
DATE	STEP		Initial Chief Eng	Action Description Chief Eng	Sign Date	&   Se	ction C	Chief Eng	QC Inspecto
1									
		· · · · · · · · · · · · · · · · · · ·							
ı	, I		1 1		, ,	1		i .	1



Dart Ae	rospace Li	td								<b>4</b>	
W/O:			WO	RK ORDER CHAN	GES						
DATE	STEP	PROCEDURE CHANGE					Date	Qty	Approval Chief Eng / Prod Mgr	Approva QC Inspector	
·								-			
Part No	):	PAR #:	Fault Categ	jory:	NCR: Yo	es N	o <b>DQ</b>	A:	_ Date: _		
Resolution:			Disposition: QA: N/C C				Closed: Date:				
NCR:			WORK ORDE	R NON-CONFORM	MANCE (N	CR)					
		Description of NC		Corrective Action Section B			Verific	ation	Approval	Approva	
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng		ın & ate	Secti		Chief Eng	QC Inspecto	
							;				
	-										
· ·											



Dart Ae	rospace L	_td								<b>&amp;</b> &
W/O:			٧	VORK ORDER C	HANGES					
DATE	STEP	PRO	CEDURE CH	IANGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approva QC Inspecto
					. •					
			· • · · · · · · · · · · · · · · · · · ·		·					
Part No	) <b>:</b>	PAR #:	Fault Ca	itegory:	NC	R: Yes	No. DQ	A:	Date: _	<del></del> -
	Res	solution:	Disposit	tion:	QA	: NC CI	osed:		Date: _	
NCR:		V	VORK OR	DER NON-CONF	ORMANCI	E (NCF	R)			
DATE	STEP	Description of NC Section A	Initial Chief Eng	Corrective Action Action Descr	Section B iption	Sign 8	k Sec	cation tion C	Approval Chief Eng	Approva QC Inspecto
1					•					
/										
,										
					· .					